

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L13	1039	drawer same (slide bearing) and (buffer damper bumper cushion fender)	USPAT; USOCR	OR	ON	2005/07/14 09:25
L14	365	13 and (separable detachable magnetic snap suction)	USPAT; USOCR	OR	ON	2005/07/14 09:28
L15	99	13 and (separable detachable)	USPAT; USOCR	OR	ON	2005/07/14 10:03
L16	651	door and (damper buffer bumper cushion fender) and air and (separable detachable)	USPAT; USOCR	OR	ON	2005/07/14 10:06
L17	135	16 and magnetic	USPAT; USOCR	OR	ON	2005/07/14 10:05
L18	170	door and (damper buffer bumper cushion fender) and (separable detachable) and magnetic	USPAT; USOCR	OR	ON	2005/07/14 10:09
L25	13	("4110868" "4303250" "4817238" "4838393" "4877226" "5157806" "5163204" "5201512" "5257680" "5471708" "5720369" "6006873" "6119832").PN. OR ("6799663").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/07/14 10:46
L26	15	("3059269" "3083399" "3555591" "3937450" "4877226" "5157806" "5471708").PN. OR ("6119832").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/07/14 11:13
L27	1	"6533617".pn.	USPAT; USOCR	OR	ON	2005/07/14 14:49
L28	1	"6553617".pn.	USPAT; USOCR	OR	ON	2005/07/14 14:50
L29	2	"0107536"	US-PGPUB; USPAT; USOCR	OR	ON	2005/07/14 14:51
L30	0	"0107536".rlan.	US-PGPUB; USPAT; USOCR	OR	ON	2005/07/14 14:51
L31	1	"7536".rlan.	US-PGPUB; USPAT; USOCR	OR	ON	2005/07/14 14:52
L32	1158116	closure device.ti.	US-PGPUB; USPAT; USOCR	OR	ON	2005/07/14 14:52
L33	2094	(closure and device).ti.	US-PGPUB; USPAT; USOCR	OR	ON	2005/07/14 14:52

L34	2	(closure and device and furniture). ti.	US-PGPUB; USPAT; USOCR	OR	ON	2005/07/14 14:53
S1	206	(drawer near slide) and (bumper damper buffer)	USPAT; USOCR	OR	ON	2005/07/08 15:23
S2	1	(drawer near slide) and (air pneumatic fluid gas)near(bumper damper buffer)	USPAT; USOCR	OR	ON	2005/07/06 15:15
S3	9552	(air pneumatic fluid gas)near(bumper damper buffer)	USPAT; USOCR	OR	ON	2005/07/06 15:15
S4	2933	(312/333,334.1,334.7,330.1,334.8). CCLS.	USPAT; USOCR	OR	OFF	2005/07/06 16:13
S6	148	S4 and (buffer damper bumper cushion fender)	USPAT; USOCR	OR	ON	2005/07/06 16:25
S7	1038	drawer same (slide bearing) and (buffer damper bumper cushion fender)	USPAT; USOCR	OR	ON	2005/07/06 16:26
S8	376	S7 and (tube cylinder pipe)	USPAT; USOCR	OR	ON	2005/07/06 16:26
S9	9	("20020066629" "5207781" "5364179" "5474375" "5580138" "6007036" "6340078" "6736471").PN. OR ("6736471" "6846053").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/07/06 16:42
S10	6	("5364179" "5474375" "5580138" "6007036" "6340078" "6736471").PN. OR ("6846053"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/07/07 08:11
S11	9552	(air pneumatic fluid gas)near(bumper damper buffer)	USPAT; USOCR	OR	ON	2005/07/07 08:11
S12	1038	drawer same (slide bearing) and (buffer damper bumper cushion fender)	USPAT; USOCR	OR	ON	2005/07/07 08:11
S13	14	S12 and S11	US-PGPUB; USPAT; USOCR	OR	ON	2005/07/07 08:11
S14	32	("0889168" "1595723" "1758550" "1902795" "2650386" "3639028" "3952365" "4003614" "4302864" "4320934" "4383707" "4494806" "4635763" "4828344" "4872239" "4894883" "4948103" "5169221" "5201512" "5207781" "5474375" "5492400" "5658058" "5890692" "6154924" "6266847" "6408483").PN. OR ("6752478").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/07/07 08:16
S15	1278	(312/333).CCLS.	USPAT; USOCR	OR	OFF	2005/07/08 15:25

S16	68	(312/334.1).CCLS.	USPAT; USOCR	OR	OFF	2005/07/08 15:25
S17	186	(312/334.7).CCLS.	USPAT; USOCR	OR	OFF	2005/07/08 15:25
S18	1315	(312/330.1).CCLS.	USPAT; USOCR	OR	OFF	2005/07/08 15:25
S19	21	(384/20).CCLS.	USPAT; USOCR	OR	OFF	2005/07/08 15:25
S20	78	(384/21).CCLS.	USPAT; USOCR	OR	OFF	2005/07/08 15:25
S21	204	(312/334.8).CCLS.	USPAT; USOCR	OR	OFF	2005/07/08 16:21
S22	430	(312/334.44).CCLS.	USPAT; USOCR	OR	OFF	2005/07/11 14:56
S23	699	(312/334.44,334.45,334.46,334.47).CCLS.	USPAT; USOCR	OR	OFF	2005/07/11 13:17
S24	430	(312/334.44).CCLS.	USPAT; USOCR	OR	OFF	2005/07/11 14:57
S25	269	S23 not S24	USPAT; USOCR	OR	ON	2005/07/11 15:25
S26	15	("1126635" "2045076" "2650386").PN. OR ("4872239").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/07/11 15:42

S27	150	("0872050" "0889168" "1126635" "1287443" "1450974" "1595723" "1758550" "1902795" "1994424" "2000916" "20020066629" "2045076" "2459012" "2650386" "2762660" "2775445" "2840437" "2940111" "3090988" "3131982" "3153333" "3259447" "3508292" "3563535" "3588198" "3639028" "3697140" "3778120" "3854785" "3952365" "3973814" "4003614" "4243277" "4302864" "4320934" "4383707" "4423914" "4494806" "4610487" "4635763" "4662761" "4737039" "4750729" "4765699" "4807868" "4828344" "4856653" "4872239" "4894883" "4948103" "5002402" "5033805" "5169221" "5201512" "5207781" "5209572" "5302016" "5344228" "5364179" "5433517" "5439284" "5466060" "5474375" "5492400" "5580138" "5658058" "5890692" "6007036" "6056379" "6113204" "6154924" "6266847" "6340078" "6408483" "6736471").PN. OR ("1172711" "1329510" "1518687" "2769196" "4494806" "4872239" "4894883" "5201512" "5356207" "6340078" "6499818" "6719386" "6736471" "6752478" "6846053").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/07/11 15:47
S28	4	("20020066629" "5207781" "5364179").PN. OR ("6736471"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/07/12 10:41
S29	13	("4110868" "4303250" "4817238" "4838393" "4877226" "5157806" "5163204" "5201512" "5257680" "5471708" "5720369" "6006873" "6119832").PN. OR ("6799663"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/07/12 11:10
S30	1	"19717937".pn.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 11:16

S31	19	"1269055".pn. "1467043".pn. "1543712".pn.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 11:17
S32	2933	(312/333,334.1,334.7,330.1,334.8). CCLS.	USPAT; USOCR	OR	OFF	2005/07/12 11:26
S33	78	(384/21,21).CCLS.	USPAT; USOCR	OR	OFF	2005/07/12 11:26
S34	0	("12and14").PN.	EPO; DERWENT	OR	OFF	2005/07/12 11:26
S35	28	S32 and S33	USPAT; USOCR	OR	ON	2005/07/12 11:27
S36	0	S32 and S33	EPO; DERWENT	OR	ON	2005/07/12 11:44
S37	28	S32 and S33	USPAT; USOCR	OR	ON	2005/07/12 11:44
S38	13	("4110868" "4303250" "4817238" "4838393" "4877226" "5157806" "5163204" "5201512" "5257680" "5471708" "5720369" "6006873" "6119832").PN. OR ("6799663"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/07/12 11:52

S39	297	("1013762" "1169538" "1212322" "1260019" "1304585" "1353218" "1450974" "1675980" "1772240" "1916571" "2000916" "2042443" "2074008" "2199145" "2421595" "2570370" "2630887" "2642845" "2644504" "2673625" "2702398" "2812533" "2944639" "2953810" "2953811" "2981534" "2985319" "2996155" "3007551" "3028620" "3053526" "3059269" "3059916" "3083399" "3107905" "3109520" "3113640" "3113644" "3129453" "3131420" "3143757" "3160233" "3160910" "3176972" "3195848" "3232597" "3249961" "3266080" "3313380" "3365189" "3392419" "3412990" "3413679" "3439913" "3462161" "3491993" "3495719" "3555591" "3563535" "3566434" "3570635" "3583530" "3605553" "3622168" "3625320" "3679069" "3696891" "3708826" "3713516" "3726419" "3738665" "3741514" "3758063" "3795391" "3796288" "3817506" "3820634" "3828651" "3831626" "3854785" "3861815" "3866964" "3885764" "3887961" "3920253" "3937450" "3948497" "3975007" "3998302" "4004662" "4011929" "4023649" "4051929" "4110868" "4113222" "4139182" "4166612" "4180346" "4203507" "4221430" "4230309" "4238104" "4240619" "4258902" "4261583" "4286802" "4318535" "4323224" "4382311" "4383595" "4396098" "4397452" "4478387" "4503951" "4558767" "4583621" "4591030" "4627591" "4628579" "4691890" "4706916" "4729458" "4733436" "4750729" "4765444").PN. OR ("4807868" "4817238" "4854554" "4856653" "4874066" "4877226" "4892279" "4920609" "4955467" "4957279" "4974794" "5157806" "5183137" "5211379" "5471708").PN. OR ("4110868" "4303250" "4817238" "4838393" "487226" "5159806" "5163204" "5201512" "5257680" "5471708" "5720369"	US-PGPUB; USPAT; USOCR	OR	ON	2005/07/12 13:51
-----	-----	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------	----	----	------------------

S40	4	("20020066629" "5207781" "5364179").PN. OR ("6736471").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/07/13 06:56
S41	4	("20020066629" "5207781" "5364179").PN. OR ("6736471").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/07/13 06:56
S42	6	("5364179" "5474375" "5580138" "6007036" "6340078" "6736471").PN. OR ("6846053").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/07/13 06:59
S43	2	"2421657".pn.	US-PGPUB; USPAT; USOCR	OR	ON	2005/07/13 06:59
S44	4	"2421657".pn.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	ON	2005/07/13 08:28
S45	68	drawer and (damper or buffer or bumper) and slid\$3	EPO; DERWENT	OR	ON	2005/07/13 07:53
S46	21	(384/20).CCLS.	USPAT; USOCR	OR	OFF	2005/07/13 07:57
S47	78	(384/21).CCLS.	USPAT; USOCR	OR	OFF	2005/07/13 07:55
S48	699	(312/334.44,334.45,334.46,334.47).CCLS.	USPAT; USOCR	OR	OFF	2005/07/13 07:55
S49	771	S46 S47 S48	USPAT; USOCR	OR	ON	2005/07/13 07:55
S50	0	("s000004").PN.	USPAT; USOCR	OR	OFF	2005/07/13 07:58
S51	2933	(312/333,334.1,334.7,330.1,334.8).CCLS.	USPAT; USOCR	OR	OFF	2005/07/13 07:58
S52	2933	S51	USPAT; USOCR	OR	ON	2005/07/13 07:58
S53	0	S51 and S46 and S47	USPAT; USOCR	OR	ON	2005/07/13 07:58
S54	3000	S51 S46 S47	USPAT; USOCR	OR	ON	2005/07/13 10:35
S55	1249	drawer and (damper or buffer or bumper) and slid\$3 not S54	USPAT; USOCR	OR	ON	2005/07/13 10:04
S56	7	"2022992".pn.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	ON	2005/07/13 08:29

S57	7	"2245157".pn.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	ON	2005/07/13 08:30
S58	6	"2245158".pn.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	ON	2005/07/13 08:31
S59	2	"0391221".pn.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	ON	2005/07/13 08:31
S60	0	"002276".pn.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	ON	2005/07/13 08:31
S61	3	"9411701".pn.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	ON	2005/07/13 08:31
S62	1	"29621957".pn.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	ON	2005/07/13 08:32
S63	1	"29616054".pn.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	ON	2005/07/13 08:32
S64	1	"29916841".pn.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	ON	2005/07/13 08:32
S65	2	"0391221".pn.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	ON	2005/07/13 08:33
S66	0	"5-317133".pn.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	ON	2005/07/13 08:33

S67	4	"317133".pn.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	ON	2005/07/13 08:44
S68	4	"4328502".pn.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	ON	2005/07/13 08:45
S69	3	"2981364".pn.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	ON	2005/07/13 08:45
S70	1	"29821364".pn.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	ON	2005/07/13 08:46
S71	1	"29913854".pn.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	ON	2005/07/13 08:46
S72	2	"19835466".pn.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	ON	2005/07/13 08:46
S73	1	"29916841".pn.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	ON	2005/07/13 08:47
S74	1	"20010282".pn.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	ON	2005/07/13 08:47
S75	3	"791984".pn.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	ON	2005/07/13 08:47
S76	5	"741984".pn.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	ON	2005/07/13 08:48

S77	4	"743032".pn.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	ON	2005/07/13 08:48
S78	84	drawer and (damper or buffer or bumper) and slid\$3 and S54	USPAT; USOCR	OR	ON	2005/07/13 10:15
S79	96	drawer and (damper or buffer or bumper) and S54	USPAT; USOCR	OR	ON	2005/07/13 10:15
S80	12	drawer and (damper or buffer or bumper) and S54 not S78	USPAT; USOCR	OR	ON	2005/07/13 10:15
S81	6	("5364179" "5474375" "5580138" "6007036" "6340078" "6736471").PN. OR ("6846053").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/07/13 10:17
S82	1039	drawer same (slide bearing) and (buffer damper bumper cushion fender)	USPAT; USOCR	OR	ON	2005/07/13 10:34
S83	99	S82 and S54	USPAT; USOCR	OR	ON	2005/07/13 10:49
S84	0	"236925".pn.	USPAT; USOCR	OR	ON	2005/07/13 10:49
S85	5	"236925".pn.	USPAT; USOCR; EPO; DERWENT	OR	ON	2005/07/13 10:49
S86	8	"1236925".pn.	USPAT; USOCR; EPO; DERWENT	OR	ON	2005/07/13 10:49